

# **CITY ASSESSMENT REPORT**

#### **Generated by**







#### **CITY NAME**


The FSM Index score indicates that the Overall FSM performance of the city is **Good.** 

Scale: Poor 0-33% | Developing 33-66% | Good 67-100%

The FSM infrastructure of the city requires improvement with a focus on - containment systems and treatment infrastructure. The enabler ecosystem assessment score indicates need for improvement in aspects of - Operation and maintenance.

The city typology and the results of each section have been summarized below.

#### **Enabler Ecosystem Assessment**



#### Infrastructure Assessment














# DETAILED ASSESSMENT REPORT – ENABLER ECOSYSTEM (1 / 3)




## DETAILED ASSESSMENT REPORT – ENABLER ECOSYSTEM (2 / 3)



## DETAILED ASSESSMENT REPORT – ENABLER ECOSYSTEM (3 / 3)




### DETAILED ASSESSMENT REPORT – INFRASTRUCTURE (1 / 2)



#### DETAILED ASSESSMENT REPORT - INFRASTRUCTURE (2 / 2)




# Households Other Buildings HH with access to HH toilet Buildings with access to toilet within the premise 62% HH with access to community/public toilet Buildings with access to toilet outside the premise 54% HH practicising OD Buildings with no access to toilet 53%











**78%** 




Adequacy of desludging vehicles and operators in the city

**INADEQUATE** 




Presence of treatment systems in and around the city

YES



4%
Re-use of treated wastewater



## **RELEVANT LEARNING MODULES**